



Photo of the Week



#596: Here, Let Me Hold It While You Do That

"This was taken about 4 hours after the crane crew gave a long lecture during the daily safety meeting about the importance of people not crossing the danger tape," our contributor writes. "Apparently, they didn't want anyone else to stand under suspended loads. The employee was using a grinder to cut the wire ties holding the covers over the bottom nozzles." The danger tape must have been meant for pedestrians.

Want more?

<< [Previous](#) | [Next](#) >>

www.public.navy.mil/comnavsafecen